



## Ordering Guide – H-3531



<b>H-3531 Pressure Sensor</b>				
<b>Pressure Range</b>	0-15 psi (34.6 ft, 10.5m)	15		
	0-30 psi (69.2 ft, 42.69m)	30		
	0-50 psi * (115ft, 71m)	50		
<b>Output Options</b>	4-20mA, SDI12, RS-485 (MODBUS), RS-232		1	
	0-5 VDC, SDI-12, Quadrature, RS-232		2	
<b>Units</b>	Feet			1
	Inches			2
	Millimeters			3
	Centimeters			4
	Meters			5
	PSI			6
<b>Cable</b>	H-3531-3PCABLE – PC Communication Cable			C

\* Considered Extended pressure range and includes an additional fee for this range.

*Example as follows:*

H-3531-15-2-5-C

H-3531 Pressure Sensor with 0-15 psi range, set to 0-5VDC output mode, with Meter Units and an RS-232 Cable

**Base Unit Includes:**

H-3531 Pressure Sensor

H-3531-7PCABLE - 7-Conductor Interface Cable; Power, SDI-12, Control

Product Literature Disk



H-3531-7PCable – Interface Cable



H-3531-3PCABLE – PC Communication Cable